

**WHOLE BUILDING VENTILATION OF  
HIGH RISE CONDOMINIUM WITH  
ELEVATED RADON FROM CONCRETE**

Bill Brodhead

WPB Enterprises

[www.WPB-Radon.com](http://www.WPB-Radon.com)

&

Tom Hatton

Clean Vapor

[www.CleanVapor.com](http://www.CleanVapor.com)

100 units in a five story building  
900 ft<sup>2</sup> to 2000 ft<sup>2</sup> units



Post stressed  
concrete slabs,  
ceilings.

Concrete walls  
surrounding the  
stair wells.

All walls & ceilings  
dry walled

Although 1<sup>st</sup> floor units are ground contact the  
surrounding area has low radon potential


# Building Layout

1st Floor is two story units


3<sup>rd</sup> – 4<sup>th</sup> – 5<sup>th</sup> Floor are single story units

Four plex (Quad) units were the most difficult to route ducts to

Four storage closets lined up on each floor



# Elevated Radon levels on every floor of the Building



## Radon Levels directly related to Ventilation Rate

If average concrete emanation rate is 60 pCi/ft<sup>2</sup>/hour and ceiling is 9 feet tall than 120 pCi enters 255 liters per hour (9 cf X 28.3)

The following ventilation rates will induce pCi/l

$$0.3 \text{ ACH} = 76 \text{ lph} \quad 120 \div 76 = 1.6 \text{ pCi/l}$$

$$0.1 \text{ ACH} = 25.5 \text{ lph} \quad 120 \div 25.5 = 4.7 \text{ pCi/l}$$

$$0.05 \text{ ACH} = 12.7 \text{ lph} \quad 120 \div 12.8 = 9.4 \text{ pCi/l}$$

# Could Granite Counter Tops be the Source?

Lets assume the kitchen has 50 ft<sup>2</sup> of granite

Granite emanates uniform 500 pCi/hr/ft<sup>2</sup>

Total emanation is  $50 \times 500 = 25,000$  pCi/hr

1000 ft<sup>2</sup> of Condo = 2000 ft<sup>2</sup> of concrete

Concrete emits 60 pCi/hr/ft<sup>2</sup>

Total emanation =  $60 \times 2000 = 120,000$  pCi/hr

Concrete produces 4.8 times more Radon  
than hottest Granite!



# Adjacent unit used ERV's installed in every unit



# Only Solution is Ventilation Increase

## Ventilation Choices

Introduction of unconditioned air (not considered)

Ventilation with Energy Recovery Ventilator (ERV)

Introduction of Central Supply Conditioned Air (CSCA)

## Pros & Cons ERV vs CSCA CSCA is more expensive

Easy to adjust airflow with CSCA (need 50 to 110 CFM)

ERV will contribute humidity - CSCA will reduce humidity

ERV requires multiple penetrations of exterior shell

ERV requires exterior penetrations be separated

ERV inlets at deck bring in odors from adjoining units

ERV's have poor cooling recovery

ERV unit takes up interior finished space

ERV ductwork requires drywall and finish work

ERV would require replacing 100 filters 2X per year

CSCA is quieter and any maintenance is non-obtrusive



Condo Association decided to have a central ventilation system distribute conditioned air to each unit.

An Engineering Company was hired to design the ventilation system

HVAC does not run a lot in the winter months

WPB was hired to determine the necessary ventilation rate and to determine if single point ventilation would reduce radon levels in bedrooms if doors were closed and HVAC was off

Knowing the:

- 1) Volume of the Space
- 2) Area of Concrete Exposure
- 3) Radon Level reduction from Induced Ventilation


Allows you to determine the:


- 1) Existing Natural Ventilation Rate
- 2) Radon Emanation Rate of the Concrete
- 3) Ventilation Rate during Previous Radon Testing
- 4) Necessary ventilation to maintain low radon levels


# Ventilation Test


10' 0"


3/16" = 1' 0"

















Unit #	pCi/ft <sup>2</sup> /hr concrete	Fan Induced ACH	0.03 ACH Mild Weather pCi/L	0.10 ACH Cold Windy pCi/L	Mild weather Bedroom closed doors No HVAC
L-504		0.20	2.1	1.6	3.1
L-504	58.0	0.25	1.7	1.4	2.6
L-504		<b>0.30</b>	<b>1.5</b>	<b>1.2</b>	<b>2.2</b>
E-619		0.20	2.4	1.8	3.6
E-619	59.0	0.25	2.0	1.6	3.0
E-619		<b>0.30</b>	<b>1.7</b>	<b>1.4</b>	<b>2.5</b>
E-511		0.20	2.6	2.0	3.8
E-511	60.0	0.25	2.1	1.6	3.0
E-511		<b>0.30</b>	<b>1.8</b>	<b>1.5</b>	<b>2.7</b>
L-408		0.20	1.4	1.1	2.1
L-408	39.0	0.25	1.2	0.9	1.7
L-408		<b>0.30</b>	<b>1.0</b>	<b>0.8</b>	<b>1.5</b>
L-318		0.20	2.6	2.0	3.8
L-318	61.0	0.25	2.1	1.7	3.1
L-318		<b>0.30</b>	<b>1.8</b>	<b>1.5</b>	<b>2.7</b>

It may not be necessary in Condominium Buildings  
to add supplemental heat to ventilation air

## Outdoor High & Low Temperatures During ventilation Test

Date	Tues	Wed	Thurs	Fri	Sat	Sun	Mon
High	43°	45°	61°	44°	45°	53°	47°
Low	24°	18°	26°	21°	13°	29°	30°

Even though temperatures were record lows for North Carolina the interior temperatures never decreased when 47 CFM of outdoor air was introduced and the unit was not occupied



## Final Ventilation Design – 100% conditioned air

Two Roof Top 20 ton – 3500 cfm units

Air supplied to each unit @

Heating 70° (21c) at 20% rh

Cooling 68° (18c) at 50% rh

Cooling cycle - ½ gal/min condensation / unit

Each Condo unit received 0.3 ACH of air

Two story units on 1<sup>st</sup> floor received 0.4 ACH to compensate for single delivery to one floor.

## Construction Issues

Post Stressed Concrete steel cables could not be cut. All slab cuts were first X-Ray scanned. Rebar could be cut.

There were utility rooms that stacked from the roof to the 1<sup>st</sup> floor that allowed two major trunks down.

All the hard ducted runs to the individual units had to be routed above a 12" drop ceiling that was already filled with other utilities

Fire stop dampers included at each floor and into each unit

## More Construction Issues

The duct into each unit include adjustable airflow damper

Most units only required a single grill above the entrance door

Some units required more elaborate duct runs that needed to be drywalled and finished.

Each floor hallway had five equally space supply diffusers.

A balancing company was used to set the adjust the final airflow to each unit




## 2 - 3500 CFM Air Handlers lifted to roof



$\frac{1}{2}$  gallon minute of  
condensation 2" drain

X-ray of slab showing post stressed steel and rebar. Engineers allowed rebar to be cut



X-Ray Company  
Owner's Car



# Slab cut by multiple core holes



Slab was 9"  
thick

# Ductwork installed above drop ceiling in the hallways



All ducts were  
carefully sealed



Duct run to the Quad units was difficult



These units had the least radon reduction

All units had balancing dampers



Fire stops installed at each fire barrier penetration

# Professional balancing done on all supply grills



Minimal intrusive supply grill in each unit



## Final Radon Reductions were excellent

Units Tested	Average Post Mitigation Radon Level
1 <sup>st</sup> Floor Quad units	2.1
1 <sup>st</sup> Floor units	1.2
1 <sup>st</sup> Floor without Quad units	0.8
3 <sup>rd</sup> Floor units	0.8
4 <sup>th</sup> Floor units	0.8
5 <sup>th</sup> Floor units	0.7
Hallways	0.6

Quad Units required extra long duct runs